Cam roller Assembly Replacement

Mag



0.040" 12" long feeler gauge

Remove all four end caps.




Two saw horses or the truck tail gate recommended.


Avoid setting motors on the ground.



00000

Removing the linkage arm is optional.







Remove all 16 of the 1/4" hex bolts holding the motor brackets on.


Step 4

Using cardboard or a piece of wood, wedge the back of the motor to the vertical gate member





Step 5





Remove the 12 point bolts, to remove the cam assembly.





Re-install both motor assemblies.

The bottom cam rollers should be making contact with the reaction fin face and be able to rotate with fingers with some resistance. Re-adjust the proximity sensor gap on both sensors (*see next page for procedure*).

Turn power on to the operator and check that the PROX JITTER is between 498 and 502 during the high speed travel in both directions.

Sensor Adjustment

The two proximity sensors are set at the factory to 0.045" from the reaction fin should be rechecked once motor are installed.

Adjustment procedure:

Turn off CB1 power to the operator.

Manually move gate halfway open.

Lift caps off of adjustment screws.

Insert 0.040" feeler gauge* between sensor A and the reaction fin.

Rotate clockwise to increase sensor gap.

Rotate counter clockwise to reduce sensor gap.

Set the A proximity sensor at 0.040"


Then turn the adjustment screw 1/4 turn clockwise.


Repeat for sensor B


Replace caps, restore power and test.


On the third cycle check the PROX JITTER on the programmer. The value should be 500 $^{+}\!\!/$ 2

Longer gates may require checking the sensor gap at two to three different points along the gate travel. These adjustments may have to be averaged throughout the length of travel.










Reaction Fin



but